Overall Unit and Item Ratings

Butte County Public Works Department Butte County Public Works

Big Chico Creek Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Butte County Public Works Department Butte County Public Works (cont.)

Lindo Channel Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Butte County Public Works Department Butte County Public Works (cont.)

Lindo Channel Diversion Weir

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

City of Sacramento

El Camino Avenue Bridge

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

Overall Unit and Item Ratings

DWR Sacramento Maintenance Yard

Cache Creek Setting Basin Weir And Drainage Structure

Overall Unit Rating	Rated Item	Item Rating
Α	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	Α
	Flap Gates	Α
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	N
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	Α

Fremont Weir

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

Overall Unit and Item Ratings

DWR Sacramento Maintenance Yard (cont.)

Knights Landing Outfall Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	N
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	Α
	Sluice/Slide Gates	N
	Electric Gate Operators	М
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	N
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	М
	Monolith Joints	N
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sacramento Maintenance Yard (cont.)

Paradise Dam

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	М
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	N
	Concrete Tilting / Settlement	N
	Concrete Foundations	N
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	М

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sacramento Maintenance Yard (cont.)

Sacramento Weir

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	N
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	М
	Concrete Tilting / Settlement	N
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	N
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard

Butte Slough Drainage Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	Α
	Trash Racks	N
	Flap Gates	Α
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	N
	Concrete Tilting / Settlement	N
	Concrete Foundations	N
	Security Fencing	N
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Butte Slough Outfall Structure

Overall Unit Rating	Rated Item	Item Rating
Α	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Colusa Weir

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Little Chico Creek Control And Weir Structures

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	Α
	Revetments	N
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Moulton Weir

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Nelson Bend

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	N
	Concrete Tilting / Settlement	N
	Concrete Foundations	N
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Sutter Bypass Weir No. 2

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Tisdale Weir

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

Overall Unit and Item Ratings

DWR Sutter Maintenance Yard (cont.)

Wadsworth Canal Weir No. 4

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lake County Watershed Protection District

Clover Creek Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
M	Photo Documentation	N
	Vegetation & Obstructions	М
	Shoaling / Sedimentation	М
	Erosion / Bank Caving	Α
	Revetments	N
	Encroachments	Α
	Culverts: Inlets / Outlets	M
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	Α
	Trash Racks	N
	Flap Gates	Α
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	N
	Concrete Tilting / Settlement	N
	Concrete Foundations	N
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	М

2012 Structure Summary Report

Overall Unit and Item Ratings

Lake County Watershed Protection District (cont.)

Highland Canal Diversion Weir And Drainage Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	М
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	N
	Encroachments	M
	Culverts: Inlets / Outlets	M
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	Α
	Trash Racks	N
	Flap Gates	Α
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	М
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Overall Unit Rating	Rated Item	Item Rating
Α	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	M
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	А

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Overall Unit Rating	Rated Item	Item Rating
Α	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	М
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Bear Creek Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	М
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Eastside Bypass Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	Α
	Safety	Α

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Eastside Bypass Drop Structure No. 1

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	М
	Revetments	N
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Eastside Bypass Drop Structure No. 2

Overall Unit Rating	Rated Item	Item Rating
Α	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	М
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Fresno River Drainage Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	Α
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Mariposa Bypass Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	А
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	A
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Mariposa Bypass Drop Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Owens Creek Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	М
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	М
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Owens Creek Overflow Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	N
	Safety	Α

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

San Joaquin River And Chowchilla Canal Bypass Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	Α
	Flap Gates	N
	Sluice/Slide Gates	M
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	N
	Trash Rakes	Α
	Other Metallic Items	Α
	Monolith Joints	Α
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

San Joaquin River Structure And Sand Slough Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	М
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	М
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Madera County FCWCA

Ash And Berenda Slough Control Structures

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	М
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	М
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	N
	Safety	М

2012 Structure Summary Report

Overall Unit and Item Ratings

Madera County FCWCA (cont.)

Fresno River Diversion Weir

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	М
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	Α
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Merced Streams Group

Black Rascal Creek Drop Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	М
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	М
	Revetments	N
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Merced Streams Group (cont.)

Owens Creek Siphon Structure

Overall Unit Rating	Rated Item	Item Rating
M	Photo Documentation	N
	Vegetation & Obstructions	М
	Shoaling / Sedimentation	U
	Erosion / Bank Caving	Α
	Revetments	N
	Encroachments	Α
	Culverts: Inlets / Outlets	U
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Reclamation District No. 0999 Netherlands

Elk Slough Inlet Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	N
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Plumas County

North Fork Feather River Diversion Channel Drop Structure No. 1 Through 7

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	N
	Safety	Α

2012 Structure Summary Report

Overall Unit and Item Ratings

Plumas County (cont.)

North Fork Feather River Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
Α	Photo Documentation	N
	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	Α
	Trash Racks	Α
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	Α

Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District

Duck Creek Diversion Weir And Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	Α
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	Α
	Monolith Joints	Α
	Safety	Α